

Oil Field Environmental Incident Summary

Incident: 20160112135631 **Date/Time of Notice:** 01/12/2016 13:56

Responsible Party: CRESCENT POINT ENERGY U.S. CORP.

Well Operator: CRESCENT POINT ENERGY U.S. CORP.

Well Name: CPEUSC ALDAG 4-36-35-164N-100W

Field Name: WEST AMBROSE

Well File #: 30622

Date Incident: 1/11/2016 **Time Incident:** 1100

Facility ID Number:

County: DIVIDE

Twp: 164 **Rng:** 100 **Sec:** 36 **Qtr:**

Location Description:

Submitted By: Chris Del Hierro

Received By:

Contact Person: Scott Van De Woestyne
555 17TH STREET, SUITE 1800
DENVER, CO 80202

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 2 | Barrels | 2 | Barrels | 2 | barrels |

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/11/2016

Clean Up Concluded: 1/11/2016

Risk Evaluation:

None

Areal Extent:

50x300 sqft

Potential Environmental Impacts:

Misted impacts to surface soil and standing snow.

Action Taken or Planned:

Recover impacted soils & clean production equipment as necessary.

Wastes Disposal Location: Secure 13 mile facility

Agencies Involved:

Updates

Date: 1/12/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

1/12/2016 at 16:38, on location. Met with site personnel. Spray came out of trailer-mounted flare located on southcentral edge of wellpad. Impact generally limited to off-site area directly adjacent to wellpad (consisting of a wheat stubble field), but according to personnel, strong winds at the time of the event carried finer mist further out into the field. Large area in field has been scraped, but there is no visible staining outside of scraped area. Cleanup is still underway; a large pile of snow from the scraping is present in the middle of the scraped area. Stained snow visible in this pile. More followup required in spring to monitor recovery of field.

Date: 1/12/2016 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release impacted area off location. Follow-up is required.

Date: 8/21/2016 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

8/21/2016 at 11:53, on location. Area that was previously impacted has been tilled and cultivated, and is currently filled with golden wheat. No visible staining or stressed area of wheat. No further follow-up required at this time.